


Homework #6

Problem 1: Determine the reactions at the supports A, B, and C, then draw the shear and moment diagrams. EI is constant.



Problem 2: Determine the moments at each support, then draw the moment diagram. Assume A is fixed and EI is constant.

