

University of Maryland


ENCE353: Introduction to Structural Analysis

In-Class Problem #3

Draw the shear and moment diagrams for the beam shown below. Make sure to label important values and their locations on the diagrams.







20

- 100



$$ZF_{x} = 0$$
 $A_{x} = 0$
 $f(x) = 0$